

Update- telephone system outage at IBC building

The issue appears to be corrupted system software. The call processing card, hard drive and flash drive are being replaced. System reprogramming will also occur.

It is anticipated installation of new hardware and software will begin early this evening.

An update will follow this evening after this work is completed, likely before 10pm.

Thank you for your patience.