

Update status- Telephone system at IBC building

The remaining issues with the IBC telephone system have been identified to be the result of software corruption, likely caused by the hardware failure yesterday.

The hardware issue has been resolved. The system software is currently in the process of being rebuilt and reinstalled.

It is anticipated this will be completed by 5pm.

We apologize for the inconvenience and thank you for your patience.