

## **RVA 3rd and 4th floor without wireless**

The network gear that provides power and network connectivity to the wireless access points has died. Networking is enroute to replace the failed gear. An update will be sent out as soon as possible. If you have any questions, please contact Danny Eaton (x5233, [dannyeaton@rice.edu](mailto:dannyeaton@rice.edu)).