

# **Allen Center basement networking issue**

A failing component was found during routine maintenance of network gear in Allen Center. The component is being replaced at this time. An all-clear message will be send out when complete. Thank you for your understanding. For any questions, please ask Dylan Jacob (dtj1@rice.edu).