

Campus Data Center Network Disruption

At approximately 2:28 pm today, one of the core network routers in Rice's primary data center failed when a hardware component went off-line. The redundancy architecture worked partly, but the traffic load caused the redundant pair to become unresponsive.